

Person seen outside of the MEWP he was using, not attached to any anchor point standing on top of an open water tank whilst proceeding to carry out installation of the cladding.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION: QUARRY
ACTIVITY: ACCESS & EGRESS & WORKING AT HEIGHT
SUB ACTIVITY: N/A

ALERT STATUS: Normal
DATE ISSUED: 11/09/2024 19:42:57
INCIDENT No: 03778