

Whilst stripping and dismantling a scaffolding inside, a 6ft tube has fallen 30ft, impacting on handrails and walkways, reaching the ground floor. An exclusion zone was in place directly underneath the dismantling operation, however the tube has fallen outside of this zone.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CEMENT PLANT	ALERT STATUS:	Normal
ACTIVITY:	MAINTENANCE & HOUSEKEEPING	DATE ISSUED:	12/09/2024 13:37:33
SUB ACTIVITY:	CEMENT	INCIDENT No:	03784