

Lifting - A piece of a concrete unit broke away whilst being stacked on another and dropped to the ground, striking operatives hard hat on its descent to the floor.

WHAT HAPPENED

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	CONCRETE PRODUCTS PLANT	ALERT STATUS:	Normal
ACTIVITY:	LOADING AND UNLOADING	DATE ISSUED:	13/09/2024 12:17:42
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	03800