

Quarry face collapse during drilling operation

WHAT HAPPENED

A contractor was on-site at the quarry and whilst drilling the first row of holes, the face collapsed with approx. 100 tonnes of material falling to the quarry floor.

Please view incident alert 4841 for more information about what happened and recommended actions.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	QUARRY	ALERT STATUS:	Normal
ACTIVITY:	QUARRYING AND FACE ACTIVITY	DATE ISSUED:	29/10/2024 12:06:19
SUB ACTIVITY:	NO SUB ACTIVITY AVAILABLE	INCIDENT No:	04842