Fatal 3 - Fall arrest systems removed putting operators at risk

WHAT HAPPENED

During a site walk around, it was noted that there were no fall arrest systems in place for several areas and personnel were working in these areas. They had previously been in place but had been moved.

LEARNING POINTS / ACTIONS TAKEN

LOCATION:	**QUARRY**	**ALERT STATUS:**	**Normal**
ACTIVITY:	**ACCESS & EGRESS & WORKING AT HEIGHT**	**DATE ISSUED:**	**09/06/2025 19:22:06**
SUB ACTIVITY:	**N/A**	**INCIDENT No:**	**04912**