


BEST PRACTICE

LOCATION: Brickworks
ACTIVITY: Maintenance & Housekeeping
SUB ACTIVITY: N/A
BEST PRACTICE No: BP2086
COUNTRY OF ORIGIN:

ARTICLE YEAR: 2021
COMPANY: Mansfield Sand Co Ltd
COMPANY LOCATION: Brick Division
COMPANY TEL: 0000

TITLE	
Safe kiln access and inspection project	
ARTICLE	
<p>Entry 21003 Winner Fatal 1,3 and 5</p> <p>The brickworks at Mansfield Sand have a large curing chamber for the bricks consisting of racking configured into 9 lanes, each containing room for 30 stacks of pallets, each stack is 19 pallets high. As a result, this is deemed a critical structure and must be maintained in good condition to remain structurally sound.</p> <p>Following an incident where someone fell and was injured, Mansfield recognised that it was necessary to improve both pedestrian and machine access to the kilns. At the same time, a more frequent inspection policy was introduced making the provision of good access even more critical.</p> <p>Please click here for more information or on additional pdf</p>	
ARTICLE IMAGES	