


BEST PRACTICE

LOCATION:	Brickworks	ARTICLE YEAR	2021
ACTIVITY:	Maintenance & Housekeeping	COMPANY:	Mansfield Sand Co Ltd
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Brick Division
BEST PRACTICE No:	BP2086	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE	
Safe kiln access and inspection project	
ARTICLE	
<p>Entry 21003 Winner Fatal 1,3 and 5</p> <p>The brickworks at Mansfield Sand have a large curing chamber for the bricks consisting of racking configured into 9 lanes, each containing room for 30 stacks of pallets, each stack is 19 pallets high. As a result, this is deemed a critical structure and must be maintained in good condition to remain structurally sound.</p> <p>Following an incident where someone fell and was injured, Mansfield recognised that it was necessary to improve both pedestrian and machine access to the kilns. At the same time, a more frequent inspection policy was introduced making the provision of good access even more critical.</p> <p>Please click here for more information or on additional pdf</p>	
ARTICLE IMAGES	