


() ! " # \$ % & ' () * + , - . / : ;

																			
% &										' # # 0									
1 2 3 . & 4 ' 5																			
<p>The brickworks at Mansfield Sand have a large curing chamber for the bricks consisting of racking configured into 9 lanes, each containing room for 30 stacks of pallets, each stack is 19 pallets high. As a result, this is deemed a critical structure and must be maintained in good condition to remain structurally sound.</p> <p>Following an incident where someone fell and was injured, Mansfield recognised that it was necessary to improve both pedestrian and machine access to the kilns. At the same time, a more frequent inspection policy was introduced making the provision of good access even more critical.</p> <p>Please & 6 for more information or on additional pdf</p>																			
/																			