

BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2024
ACTIVITY:	Maintenance & Housekeeping	COMPANY:	CEMEX UK
SUB ACTIVITY:	Screens & washers	COMPANY LOCATION:	Swinderby Quarry
BEST PRACTICE No:	BP2212	COMPANY TEL:	0000
COUNTRY OF ORIGIN:			

TITLE

Improved washer barrel access. Topic 2

ARTICLE

FINALIST - TOPIC 2

Access to washer barrels has for a long time been a problem due to poor design or even a lack specifically designed proprietary access.

At Swinderbury Quarry access to the washer barrel is required for routine inspections and maintenance which exposed operators to risk associated with climbing into the barrel and those associated with an enclosed and confined space.

Traditionally, access to the unit was tough, climbing through a trommel or improvised access from a nearby walkway not designed for access to the barrel.

CEMEX decided to develop a solution that would eliminate these hazards.

Please view the video to see the solution they developed in operation

ARTICLE IMAGES