**BEST PRACTICE** 

LOCATION: Transport

ACTIVITY: Access & Egress & Working at

Height

N/A

**BEST PRACTICE No: BP2216** 

COUNTRY OF ORIGIN:

**SUB ACTIVITY:** 

ARTICLE YEAR 2024

COMPANY: Smiths and Sons (Bletchington)
COMPANY England Marks have

LOCATION: Enslow Workshop

COMPANY TEL: 0000

## TITLE

Safe access and egress into tipper bodies. - Topic 3

## **ARTICLE**

## **FINALIST - TOPIC 3**

During maintenance activities at the Enslow workshop, there is a requirement to gain access into the tipper trailers used within the business, this includes a variety of body configurations 2-3-4 axled vehicles.

It had been identified that the mechanics using a combination of steps / platforms fitted to the vehicles and step ladders from ground level was inherently unsafe, a fall could result in a serious injury.

Please watch the video to see the solution that was applied.

	ΕI		