BEST PRACTICE

LOCATION: Quarry ARTICLE YEAR 2006

ACTIVITY: Occupational Health COMPANY: CEMEX UK Materials

SUB ACTIVITY: PPE COMPANY LOCATION: Dove Holes Quarry, Derbyshire

BEST PRACTICE No: BP300 COMPANY TEL: 01298 77531

COUNTRY OF ORIGIN: United Kingdom

TITLE

Mechanised greasing system

ARTICLE

Greasing the machinery and equipment was a manual task that required the operative to continually climb up and down a ladder. Using the greasing gun also brought risks of repetitive strain injuries. The problem has been addressed by installing a small compressor onto the back of a wagon, along with pneumatic greasing equipment and an inertia hose reel. Once the lightweight reel has been pulled out and attached to the grease nipple, the compressor will do the rest.

ARTICLE IMAGES