

## BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Manual handling and storage	COMPANY:	Aggregate Industries
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Holme Park Quarry, Lancashire
BEST PRACTICE No:	BP317	COMPANY TEL:	01524 781441
COUNTRY OF ORIGIN:	United Kingdom		

### TITLE

**Crusher access**

### ARTICLE

Maintenance, repairs and inspection of the quarry's Mansfield crushers, created difficulties regarding manual handling, the lifting operations involving a crane, added to which, access for inspection, repairs and adjustments was poor.

It was decided to create a hydraulically operated door and hinged front panel to remedy these health and safety issues. This also included a mechanism for retaining the top hinged door whilst open. This system was then applied to the remaining crushers.

### ARTICLE IMAGES

