

BEST PRACTICE

LOCATION: Quarry
ACTIVITY: Occupational Health
SUB ACTIVITY: Vibration
BEST PRACTICE No: BP328
COUNTRY OF ORIGIN: United Kingdom

ARTICLE YEAR: 2006
COMPANY: Hanson Bath & Portland Stone
COMPANY LOCATION: Avon Mill Lane, Somerset
COMPANY TEL: 01373 452415

TITLE

Eliminating Vibration White Finger

ARTICLE

During the extraction process of dimension stone, the use of powered hand tools had resulted in cases of vibration white finger (VWF). The measures to counter this problem began in 2002 and, following several years of research, the target to eliminate VWF was achieved.

The studies carried out in conjunction with HSE and the Mines Inspectorate concluded that the existing proprietary powered hand tools marketed in the UK did not comply with the HSE guidance on safe vibration levels and that a more radical solution to the problem was needed.

The main thrust of the development programme was aimed at eliminating the use of hand held power tools for "breaking out" and "trimming" of block stones – which is where most of the vibration exposure occurs.

Today, the activities associated with extraction of dimension stone at Bath Mines are completely mechanised with no employee being at the risk of exposure to VWF.

ARTICLE IMAGES