

## BEST PRACTICE

LOCATION: Quarry  
ACTIVITY: Production and Processing  
SUB ACTIVITY: Aggregate processing  
BEST PRACTICE No: BP379  
COUNTRY OF ORIGIN: United Kingdom

ARTICLE YEAR: 2006  
COMPANY: CEMEX  
COMPANY LOCATION: Dove Holes Quarry, Derbyshire  
COMPANY TEL: 01298 77531

|  |
|--|
| <b>TITLE</b>   |
| <b>Dumper load cameras</b>   |
| <b>ARTICLE</b>   |
| During inclement weather, dumper drivers used to regularly leave the cab to check that the load was being distributed evenly and was not overhanging the sides. To negate these need for this action, the site decided to fit another rear-view CCTV camera on the side of the vehicle, overlooking the body. It thus became possible for the driver to see the load on the monitor without having to leave the cab. |
| <b>ARTICLE IMAGES</b>  |
|  |