**BEST PRACTICE** 

LOCATION: Quarry ARTICLE YEAR 2006
ACTIVITY: Access & Egress & Working at COMPANY: CEMEX

Height COMPANY: CEMEX

N/A COMPANY Hartley Quarry and Coating Plant,

SUB ACTIVITY: N/A COMPANY Hartley C LOCATION: Cumbria

BEST PRACTICE BP405 COMPANY TEL: 017683 71479

COUNTRY OF United Kingdom United Kingdom

## TITLE

## **Hinged ladder**

## **ARTICLE**

Occasionally, this coating plant requires access to view the condition and contents of the cold feed aggregate bins and the clearance of material build-up from the corners of the bin. The old steps and ladder were repeatedly damaged by the loading shovel feeding the bin and so were replaced with a hinged ladder, which can be swung out of the working area.

## **ARTICLE IMAGES**