

BEST PRACTICE

LOCATION:	Quarry	ARTICLE YEAR	2006
ACTIVITY:	Access & Egress & Working at Height	COMPANY:	CEMEX
SUB ACTIVITY:	N/A	COMPANY LOCATION:	Denge Quarry, Kent
BEST PRACTICE No:	BP406	COMPANY TEL:	01797 320422
COUNTRY OF ORIGIN:	United Kingdom		

TITLE
Accessing a Linatex sand tower
ARTICLE
<p>Accessing the site's new Linatex sand tower for routine maintenance work has been made safer by the fabrication of a mobile platform. Concerns arose about accessing the tower's three-foot cyclone extension to undo the bolts and allow the cyclone to be lowered to the ground by a crane. An operator would have to stand on the handrails whilst wearing a safety harness.</p> <p>This process has been improved by building an extension walkway / platform, complete with handrails, kickboards and self-closing gate, which can be lifted into place using a crane.</p>
ARTICLE IMAGES