


BEST PRACTICE

LOCATION: Asphalt/Coating plant ARTICLE YEAR: 2011
ACTIVITY: Maintenance & Housekeeping COMPANY: John Wainwright & Co Ltd
SUB ACTIVITY: N/A COMPANY LOCATION: Moons Hill Quarry
BEST PRACTICE No: BP754 COMPANY TEL: 01749 840274
COUNTRY OF ORIGIN: United Kingdom

TITLE	
New access hatches within the hot stone bins reduce risks	
ARTICLE	
<p>Description</p> <p>The asphalt plant had a top access door to each of its seven hot stone bins. Maintenance work within the bins was difficult because of the restrictive work area and single access route. A series of inter-connecting access hatches was created within each hot stone bin wall so that maintenance crews could access a bin from both sides. In addition, if they need to work in any other bin, they can now easily do so, without having to repeatedly climb in and out of the top access door.</p> <p>Benefits</p> <p>Improved working environment</p> <p>Reduced risk of falls and working in confined spaces</p> <p>Significantly improved emergency evacuation procedures.</p>	
ARTICLE IMAGES	