BEST PRACTICE

ARTICLE YEAR

2011

LOCATION: Quarry

ACTIVITY: Manual handling and storage **Francis Flower COMPANY: SUB ACTIVITY: COMPANY LOCATION: Guerney Slade** N/A **BEST PRACTICE No: BP766 COMPANY TEL:** 01749 841 500

COUNTRY OF ORIGIN: United Kingdom

TITLE

Mechanical chute closing device

ARTICLE

Description

To alter the flow of material through a feed chute involved an individual trying to manipulate a steel plate located eight feet off the ground. The operation was undertaken several times a day. It was a very strenuous activity sometimes requiring a sledge hammer. It was undertaken in a poorly lit, noisy and cramped space with the potential for a fall.

The plant fitter designed, fabricated and installed a system that replaced the steel plate with a cut off slide that can be slid in and out by the use of a chain pulley system operated from ground level.

Benefits

- The feed control can be made quickly and accurately
- There is no manual handling
 The risk of a fall has been removed

ARTICLE IMAGES

Click image to enlarge

